

OFFICE OF THE INSPECTOR GENERAL, BORDER SECURITY FORCE,
NORTH BENGAL FRONTIER, PO-KADAMTALA, DISTT- DARJEELING,
WEST BENGAL-734011

/// BUILDING SAFETY CERTIFICATE ///

It is certified that the Senior Secondary School building at BSF Campus Kadamtala was inspected and building seems to be structurally sound and safe as per visual inspection.

Place : KADAMTALA

Dated : 15 May 2026




15/05/2026
[SANJAI KUMAR JHA]
Dy Comdt (Works)/EE
FTR HQ BSF NB
उप कमा. (कार्य)/अधिआमि
DC (WORKS) / EE
क्र० मु० सी. सु. ब., उ. ब. कदमतला
FTR HQ BSF NB Kadamtala


OFFICE OF THE INSPECTOR GENERAL, BORDER SECURITY FORCE,
NORTH BENGAL FRONTIER, PO-KADAMTALA, DISTT- DARJEELING,
WEST BENGAL-734011

/// ELECTRICAL SAFETY CERTIFICATE ///

It is certified that the Senior Secondary School building at BSF Campus Kadamtala was inspected from electrical side and it seems to be structurally sound and safe as per inspection.

Place : KADAMTALA

Dated : 18th May 2026



Dy Comdt (ELECT)/EE

FTR HQ BSF NB

DY COMDT/EE (ELECT)

उप समादेष्टा / अधिशासी अभियंता (विद्युत)

Frontier Headquarter, North Bengal

सीमान्त मुख्यालय सी० सु० बल ३० ब०

